

General Environmental Incident Summary

Incident: 3474 **Date/Time Notice:** 9/24/2014 **DEM Incident No:**

Responsible Party: JEROME P KILLORAN DBA KILLORAN TRUCKING

Date Incident: 9/24/2014 **Time Incident:** **Duration:**

County: Stark **Twp:** 144 **Rng:** 95 **Sec:** 31 **Qtr:**

Lat: 47.24170 **Long:** -102.79300 **Method:** Interpolation from map

Location Description: Bar ditch along EB 12th St.

Submitted By: RJ Johnson

Affiliation:

Address: 6205 Chapel Hill Blvd, Suite

City: Plano

State: TX

Zip: 75093

Received By:

Contact Person:

PO BOX 145
BUFFALO, ND 58011

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 65.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Driver of a tractor-trailer lost control and traveled into ditch. As a result, a saddle fuel tank on the tractor was punctured.

Risk Evaluation:

No immediate threat

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

Threat to soil

Action Taken or Planned:

Hazmat response team from USES has responded to begin corrective actions and remediate the impacted soil.

Wastes Disposal Location: Pending

Agencies Involved: Local Law Enforcement

Updates

Date: 9/24/2014 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 65 gallons of diesel fuel were released from a saddle tank of a tractor-trailer into the ditch area along 12th St. SW, approximately 1.75 miles northwest of Manning, N.D. Sub-contractor has responded and has begun corrective measures to remediate the impacted soils. Followup is required to ascertain corrective action and necessary cleanup of the impact.

Date: 10/1/2014 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

10/1/2014 at 9:45, on location. Four covered rollofs at location within Dunn County, not Stark, at intersection of Highway 22 and 12th Street.. From observing tracks and phone conversation with report contact, it appears semi heading east on 12th Street missed turn on to Highway 22 due to weather and went into ditch and up hill slope on east side of 22. Scraped area in ditch and up hill slope. Approx 1-foot-deep excavation at end of scraped area. No visible staining to vegetation outside scraped area, and no visible staining in scraped area. No sheen visible on standing water in ditch from recent rains.

Date: 11/12/2014 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

11/12/2014 at 14:07, on location. Rollofs no longer on site.

Date: 12/19/2014 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

Final report received from responsible party.